Group 2 - 2021 IEBC Code Change Proposals

Date Received	Proponent	Code	Section	Subject	Log Number	Revision	TAG Action	Committee Action	Council Action
3/1/2022	Kerry Sutton American Concrete Institute	IEBC	405.1.1	Repair of structural concrete in accordane with ACI 562	21-GP2-002				
3/7/2022	Washington Association of Building Officials Technical Code Development Committee	IEBC	305.8.3	Platform lifts	21-GP2-004				
3/7/2022	Washington Association of Building Officials Technical Code Development Committee	IEBC	306.7.1	Alterations affecting an area containing a primary function.	21-GP2-005				
3/7/2022	Washington Association of Building Officials Technical Code Development Committee	IEBC	306.7.1	Alterations affecting an area containing a primary function.	21-GP2-006				
3/7/2022	Washington Association of Building Officials Technical Code Development Committee	IEBC	306.7.8	Platform lifts	21-GP2-007				
4/8/2022	WABO Technical Code Development	IEBC	503.19, 805.5	Seismic requirements for alteration of URM or hollow clay tile buildings increasing occupant load	21-GP2-018				
4/7/2022	Sue Coffman	IEBC	Chapter 2	Substantial Damage, Substantial Improvement definitions using ICC Building Valuation	21-GP2-029				
4/7/2022	Sue Coffman	IEBC	603.1, 604.1	Level of Alteration	21-GP2-030				
4/8/2022	Ardel Jala in behalf of WABO	IEBC	306.6	LULA Elevators	21-GP2-054				
4/8/2022	Jenifer Gilliland in behalf of WABO	IEBC	401.2, 401.4	Demolition, replacement and repair	21-GP2-055				
4/8/2022	Nathalie Boeholt in behalf of WABO	IEBC	503.13, 805.4	Voluntary lateral force-resisting system alterations	21-GP2-056				