			IBC TAG Existing A	mendmen	t Review		
Summary:	Repeal existing state amenda	ment 116	Keep existing amendment as	modified 41		Keep existing amendme	ent 164
Last Updated 3/15/2021						May include renumbering	
		2018 IBC		2021 IBC	TAG Member	TAG	
WAC	Title or Subject	Number	Title or Subject	Number	Recommendation	Recommendation	Comments
			00 G	eneral			
TAG Member: Staff							
51-50-001	Authority.	NA	Authority.	NA	Keep existing amendment	1/27/2021 Accept Recommendation	
<u> </u>						1/27/2021 Accept	
51-50-002	Purpose.	NA	Purpose.	NA	Keep existing amendment	Recommendation	
	1,000				Keep existing amendment as	1/27/2021 Accept	
51-50-003	International Building Code.	NA	International Building Code.	NA	modified.	Recommendation	Update to 2021 Code
	International Building Code		International Building Code				
	requirements for barrier-free		requirements for barrier-free		Keep existing amendment as		Change from ICC A117.1-2009 to
<u>51-50-005</u>	accessibility.	NA	accessibility.	NA	modified.	1/27/2021 Go with 2017	ICC A117.1 2017
						1/27/2021 Accept	
51-50-007	Exceptions.	NA	Exceptions.	NA	Keep existing amendment	Recommendation	
					Keep existing amendment as	1/27/2021 Accept	
51-50-008	Implementation.	NA	Implementation.	NA	modified	Recommendation	Update to July 1, 2023
						1/27/2021 Prepare for	
						TAG review a draft	
					Keep existing amendment as	proposal to move this	
	Recyclable materials, compost,		Recyclable materials, compost,		modified; consider moving to	into the body of the	See proposal for Chapter 4,
51-50-009	and solid waste storage.	NA	and solid waste storage.	NA	the body of the Code	code.	Section 430
			01 Scope and	Administrat	ion		
TAG Member: Sue Coffma	an an		or scope and	, turming er ac	.011		
TAG MEMBEL Sue Comme	Temporary structures and					1/27/2021 Accept	
<u>51-50-0108</u>	uses.	108.1	General	Same	Keep existing amendment	Recommendation	
<u> </u>	uses.	100.1	Type IV-A, IV-B, and IV-C	Jame	Reep existing amendment	Recommendation	
			connection protection			1/27/2021 Accept	
<u>51-50-0110</u>	Section inspections.	110.3.5	inspection	Same	Keep existing amendment	Recommendation	
31-30-0110	Section inspections.	110.5.5	Lath, gypsum board and	Jame	Reep existing amendment	Recommendation	
			gypsum panel product			1/27/2021 Accept	
		110.3.6	inspection	Same	Keep existing amendment	Recommendation	
		110.3.0	Inspection	Same	Reep existing amendment	Recommendation	
			Weather-exposed balcony and			1/27/2021 Accept	
		110.3.7	walking surface waterproofing	Same	Keep existing amendment	Recommendation	
		110.3./	Fire- and smoke-resistant	Jaille	veeh existing amenument	1/27/2021 Accept	
		110.3.8	penetrations	Same	Keep existing amendment	Recommendation	
	+	110.3.6	peneriations	Janne	veeh evisting amenument	1/27/2021 Accept	
		110.3.9	Energy efficiency inspections	Same	Keep existing amendment	Recommendation	
	+	110.3.10	Other inspections	Same	Keep existing amendment	Recommendation	1
		110.3.10	Special inspections	Same	Keep existing amendment	Recommendation	
				1		Recommendation	
		110.3.12	Final inspection	Same	Keep existing amendment	Recommendation	1

					1	4/27/2024	
		440 2 42 4	Flood bosond documentation	C	Kana asiatisa asaa daa aat	1/27/2021 Accept	1
		110.3.12.1	Flood hazard documentation	Same	Keep existing amendment	Recommendation	
							<u> </u>
			02 Def	finitions			
TAG Member: Damen Jeg							
<u>51-50-0200</u>	Chapter 2—Definitions.		Definitions	Same			
						1/27/2021 Accept	1
			ADULT FAMILY HOME		Keep existing amendment	Recommendation	Unique to WA State
						1/27/2021 Accept	1
			ASSISTED LIVING FACILITY		Keep existing amendment	Recommendation	Unique to WA State
						1/27/2021 Accept	1
			BOTTLE FILLING STATION		Keep existing amendment	Recommendation	Unique to WA State
						1/27/2021 Accept	1
			CHILD CARE		Keep existing amendment	Recommendation	Unique to WA State
						1/27/2021 Accept	1
			CHILD CARE, FAMILY HOME		Keep existing amendment	Recommendation	Unique to WA State
						1/27/2021 Accept	1
			CLIMATE ZONE		Keep existing amendment	Recommendation	Modified model code language
						1/27/2021 Accept	1
			CLUSTER		Keep existing amendment	Recommendation	Unique to WA State
			EFFICIENCY DWELLING UNIT		Keep existing amendment		Unique to WA State
			HOSPICE CARE CENTER		Keep existing amendment		Unique to WA State
							1
					Repeal state amendment; no		1
			MASS TIMBER		state amendment is necessary		Addressed in the Model code
			NIGHTCLUB		Keep existing amendment		Unique to WA State
			NONCOMBUSTIBLE		Reneal state amendment, no		1
			PROTECTION (For MASS TIMBER).		Repeal state amendment; no state amendment is necessary		Addressed in the Model code
			PORTABLE SCHOOL		state amendment is necessary		Addressed in the Model code
			CLASSROOM		Keep existing amendment		Unique to WA State
			CLASSICOTO		Reep existing amendment		offique to WA State
			RESIDENTIAL SLEEPING SUITES		Keep existing amendment		Unique to WA State
			SMALL BUSINESS		Keep existing amendment		Unique to WA State
			STAGED EVACUATION		Keep existing amendment		Unique to WA State
			STAGED EVACOATION		Recp existing unicitativent		ornique to WA State
					Repeal state amendment; no		1
			WALL, LOAD-BEARING		state amendment is necessary		Addressed in the the Model code
			, === == ======		7		
							1
						Accept recommendation	1
			03 Occupancy Cla	ssification and	Use		
TAG Member: Al Spaulding	,		oo oodapaney ela	unon uno			
TAG MEMBEL AT Spauluing	Section 303—Assembly Group				1		
51-50-0303	· ·	303.4	Assembly Group A-3	Same	Keep existing amendment		1
21-20-0303	Section 305—Educational	555.7	7.53cmbly Group A-3	Same	neep existing amenument		
51-50-0305	Group E.	305.2.4	Family home child care	Same	Keep existing amendment		1
<u>51 50 0505</u>	5.54p E.	555.E.T	Moderate-hazard factory	Same	Keep existing amendment as		Add new 2021 language for two
51-50-0306	Section 306—Factory Group F.	306.2	industrial, Group F-1	Same	modified.		new processes
<u>51 50 0500</u>	ractory Group 1.	330.2	Iaaatiai, Group i I	- Carrie			processes

	Section 308—Institutional						Consider omitting this reference
<u>51-50-0308</u>	Group I.	308.1.1	Definitions	Same	Keep existing amendment		redundant
							Coordinate with 308.2.6 and w
		308.2	Institutional Group I-1	Same	Keep existing amendment		any potential new proposal
		308.2.5	Adult family homes	Same	Keep existing amendment		
		308.2.6	Licensed care facilities	Same	See 308.2		
		308.3	Institutional Group I-2	Same	Keep existing amendment		
		308.5.5	Family home child care	Same	Keep existing amendment		
	Section 309—Mercantile						
<u>51-50-0309</u>	Group M.	309.1	Mercantile Group M	Same	Keep existing amendment		
	Section 310—Residential						
<u>51-50-0310</u>	Group R.	310.4	Residential Group R-2	310.3	Keep existing amendment		Double check section number
							Double check section number
			Adult family homes, family				Proposal considered to suppo
		310.4.3	home child care	310.4.3	Keep existing amendment		legislation
		310.4.4	Foster family care homes	310.4.4	Keep existing amendment		Double check section number
		310.5	Residential Group R-4	310.5	Keep existing amendment		Double check section number
						Agree with	
						recommendations	
	•	•	C		n Ossumanau and Has	•	·
		04	Special detailed Requireme	ints Based o	n Occupancy and USE		
C Mamban Al Sua	مالداد	04	Special detailed Requireme	ents Based o	n Occupancy and Ose		
G Member: Al Spa	ulding	04	Special detailed Requireme	ents Based o	n Occupancy and Ose	ı	1
G Member: Al Spa		04		ents Based o			
	Section 403—High-rise		Water supply to required fire		Amendment no longer needed,		
G Member: Al Spat 51-50-0403		403.3.2	Water supply to required fire pumps	Same	Amendment no longer needed, addressed by model code		
	Section 403—High-rise		Water supply to required fire		Amendment no longer needed, addressed by model code Keep existing amendment		
	Section 403—High-rise	403.3.2 403.4.8.3	Water supply to required fire pumps Standby power loads	Same Same	Amendment no longer needed, addressed by model code Keep existing amendment Keep existing amendment as		9
	Section 403—High-rise	403.3.2	Water supply to required fire pumps	Same	Amendment no longer needed, addressed by model code Keep existing amendment Keep existing amendment as modified		and code reference
	Section 403—High-rise	403.3.2 403.4.8.3 403.5.4	Water supply to required fire pumps Standby power loads Smokeproof enclosures	Same Same	Amendment no longer needed, addressed by model code Keep existing amendment Keep existing amendment as modified Keep existing amendment as		and code reference This should be new WAC 51-5
	Section 403—High-rise	403.3.2 403.4.8.3	Water supply to required fire pumps Standby power loads	Same Same	Amendment no longer needed, addressed by model code Keep existing amendment Keep existing amendment as modified		Check the numbering for sect and code reference This should be new WAC 51-5 405 and check code reference
	Section 403—High-rise	403.3.2 403.4.8.3 403.5.4	Water supply to required fire pumps Standby power loads Smokeproof enclosures	Same Same	Amendment no longer needed, addressed by model code Keep existing amendment Keep existing amendment as modified Keep existing amendment as		and code reference This should be new WAC 51-5 405 and check code reference
	Section 403—High-rise	403.3.2 403.4.8.3 403.5.4	Water supply to required fire pumps Standby power loads Smokeproof enclosures	Same Same	Amendment no longer needed, addressed by model code Keep existing amendment Keep existing amendment as modified Keep existing amendment as		and code reference This should be new WAC 51-5 405 and check code reference Review new language for this
	Section 403—High-rise	403.3.2 403.4.8.3 403.5.4	Water supply to required fire pumps Standby power loads Smokeproof enclosures	Same Same	Amendment no longer needed, addressed by model code Keep existing amendment Keep existing amendment as modified Keep existing amendment as		and code reference This should be new WAC 51-5 405 and check code reference Review new language for this section in 2021 and make sur
	Section 403—High-rise	403.3.2 403.4.8.3 403.5.4	Water supply to required fire pumps Standby power loads Smokeproof enclosures	Same Same	Amendment no longer needed, addressed by model code Keep existing amendment Keep existing amendment as modified Keep existing amendment as		and code reference This should be new WAC 51-5 405 and check code reference Review new language for this section in 2021 and make sur- still correlates Staff
	Section 403—High-rise	403.3.2 403.4.8.3 403.5.4	Water supply to required fire pumps Standby power loads Smokeproof enclosures	Same Same	Amendment no longer needed, addressed by model code Keep existing amendment Keep existing amendment as modified Keep existing amendment as		and code reference This should be new WAC 51-5 405 and check code reference Review new language for this section in 2021 and make sur still correlates Staff recommendation: The ration
	Section 403—High-rise	403.3.2 403.4.8.3 403.5.4	Water supply to required fire pumps Standby power loads Smokeproof enclosures	Same Same	Amendment no longer needed, addressed by model code Keep existing amendment Keep existing amendment as modified Keep existing amendment as		and code reference This should be new WAC 51-5 405 and check code reference Review new language for this section in 2021 and make sur still correlates Staff recommendation: The ration for the existing amendment
	Section 403—High-rise	403.3.2 403.4.8.3 403.5.4	Water supply to required fire pumps Standby power loads Smokeproof enclosures	Same Same	Amendment no longer needed, addressed by model code Keep existing amendment Keep existing amendment as modified Keep existing amendment as		and code reference This should be new WAC 51-5405 and check code reference Review new language for this section in 2021 and make sur still correlates Staff recommendation: The ration for the existing amendment (delete the exception allowing)
	Section 403—High-rise	403.3.2 403.4.8.3 403.5.4	Water supply to required fire pumps Standby power loads Smokeproof enclosures	Same Same	Amendment no longer needed, addressed by model code Keep existing amendment Keep existing amendment as modified Keep existing amendment as		and code reference This should be new WAC 51-5405 and check code reference Review new language for this section in 2021 and make sur still correlates Staff recommendation: The ration for the existing amendment (delete the exception allowing)
	Section 403—High-rise	403.3.2 403.4.8.3 403.5.4	Water supply to required fire pumps Standby power loads Smokeproof enclosures	Same Same	Amendment no longer needed, addressed by model code Keep existing amendment Keep existing amendment as modified Keep existing amendment as		and code reference This should be new WAC 51-5 405 and check code reference Review new language for this section in 2021 and make sur still correlates Staff recommendation: The ration for the existing amendment (delete the exception allowing 125 feet travel distance) is to
	Section 403—High-rise	403.3.2 403.4.8.3 403.5.4	Water supply to required fire pumps Standby power loads Smokeproof enclosures	Same Same	Amendment no longer needed, addressed by model code Keep existing amendment Keep existing amendment as modified Keep existing amendment as		and code reference This should be new WAC 51-5405 and check code reference Review new language for this section in 2021 and make sur still correlates Staff recommendation: The ration for the existing amendment (delete the exception allowing 125 feet travel distance) is to avoid conflicts with the feder
	Section 403—High-rise	403.3.2 403.4.8.3 403.5.4	Water supply to required fire pumps Standby power loads Smokeproof enclosures	Same Same	Amendment no longer needed, addressed by model code Keep existing amendment Keep existing amendment as modified Keep existing amendment as		and code reference This should be new WAC 51-5 405 and check code reference Review new language for this section in 2021 and make sur still correlates Staff recommendation: The ration for the existing amendment (delete the exception allowing 125 feet travel distance) is to avoid conflicts with the federal
	Section 403—High-rise	403.3.2 403.4.8.3 403.5.4	Water supply to required fire pumps Standby power loads Smokeproof enclosures	Same Same	Amendment no longer needed, addressed by model code Keep existing amendment Keep existing amendment as modified Keep existing amendment as		and code reference This should be new WAC 51-5405 and check code reference Review new language for this section in 2021 and make sur still correlates Staff recommendation: The ration for the existing amendment (delete the exception allowing 125 feet travel distance) is to avoid conflicts with the feder requirements. The model code
	Section 403—High-rise	403.3.2 403.4.8.3 403.5.4	Water supply to required fire pumps Standby power loads Smokeproof enclosures	Same Same	Amendment no longer needed, addressed by model code Keep existing amendment Keep existing amendment as modified Keep existing amendment as		and code reference This should be new WAC 51-5 405 and check code reference Review new language for this section in 2021 and make sur still correlates Staff recommendation: The ration for the existing amendment (delete the exception allowing 125 feet travel distance) is to avoid conflicts with the federal requirements. The model code modified to reflect recent changes in the federal rules.
	Section 403—High-rise	403.3.2 403.4.8.3 403.5.4	Water supply to required fire pumps Standby power loads Smokeproof enclosures	Same Same	Amendment no longer needed, addressed by model code Keep existing amendment Keep existing amendment as modified Keep existing amendment as		and code reference This should be new WAC 51-5 405 and check code reference Review new language for this section in 2021 and make sur still correlates Staff recommendation: The ration for the existing amendment (delete the exception allowing 125 feet travel distance) is to avoid conflicts with the federal requirements. The model cod modified to reflect recent changes in the federal rules. Recommend adopting the model.
51-50-0403	Section 403—High-rise buildings.	403.3.2 403.4.8.3 403.5.4 405.7.2	Water supply to required fire pumps Standby power loads Smokeproof enclosures Smokeproof enclosure	Same Same Same	Amendment no longer needed, addressed by model code Keep existing amendment Keep existing amendment as modified Keep existing amendment as		and code reference This should be new WAC 51-5 405 and check code reference Review new language for this section in 2021 and make sur still correlates Staff recommendation: The ration for the existing amendment (delete the exception allowing 125 feet travel distance) is to avoid conflicts with the federal requirements. The model cod modified to reflect recent changes in the federal rules. Recommend adopting the mocode language and repealing.
	Section 403—High-rise	403.3.2 403.4.8.3 403.5.4 405.7.2	Water supply to required fire pumps Standby power loads Smokeproof enclosures	Same Same	Amendment no longer needed, addressed by model code Keep existing amendment Keep existing amendment as modified Keep existing amendment as modified		and code reference This should be new WAC 51-5 405 and check code reference Review new language for this section in 2021 and make sure still correlates Staff recommendation: The rations for the existing amendment (delete the exception allowing 125 feet travel distance) is to avoid conflicts with the federal requirements. The model cod modified to reflect recent

		412.8.3	Means of egress	412.7.3	Keep existing amendment	_	Check numbering
	Section 420—Groups I-1, R-1, R						
<u>51-50-0420</u>	2, R-3.	420.2	Separation walls	Same	Keep existing amendment		
					Keep existing amendment as		Check section references
		420.11	Adult family homes	420.12	modified.		throughout full section
		420.11.1	Sleeping room classification	420.12.1	Keep existing amendment		
			Types of locking devices and				
		420.11.2	door activation	420.12.2	Keep existing amendment		
			Smoke and carbon monoxide				
		420.11.3	alarm requirements	420.12.3	Keep existing amendment		
		420.11.4	Escape windows and doors	420.12.4	Keep existing amendment		
		420.11.5	Grab bar general requirements	420.12.5	Keep existing amendment		May need cross referencing with new A117.1. Staff Comment: O.K.; no conflicts with ANSI A117.1
		420.11.6	Shower stalls	420.12.6	Keep existing amendment Keep state amendment but		May need cross referencing with new A117.1. Staff Comment: Existing amendment requires 30"x48" min. shower stall; this doesn't align with the requirements for accessible showers in ANSI A117.1. At the same time 420.11.5 refers to ANSI A117.1 for grab bars for shower stalls. It is impossible to meet the size and location requirements for grab bars if the shower compartment doesn't meet the size requirements for accessible showers.
		420.42	Lineared core cooking feetlistics	420 42**	look at integration with 420.8,		May need code proposal to
	Section 422—Ambulatory care	420.12	Licensed care cooking facilities	420.13	420.9		better integrate to model code
E1 E0 0422	facilities.	422.3.1	Means of egress	Same	Keep existing amendment		
<u>51-50-0422</u>	Section 427—Electric vehicle	422.3.1	INICALIS OF ERIESS	Jaille	weeh existing amendment		This is being moved to 51-50-
51-50-0427	charging infrastructure.	429.1	Scope	Same	Keep existing amendment		0429
<u>31*30*0427</u>	charging initiastructure.	723.1	эсорс	Jame	Rec p existing amendment		Need to correct internal section
			Required electric vehicle		Keen existing amondment as		references as well in entire
		429.2	Required electric vehicle charging infrastructure	Same	Keep existing amendment as modified		section
		429.3	Electrical room(s)	Same			SECTION
		443.3	Electrical room(s)	Jaille	Keep existing amendment		
		429.4	infrastructure	Same	Koon ovicting amondment		
		423.4		Sallie	Keep existing amendment		
			Electric vehicle charging				
		420 5	infrastructure for accessible	Como	Kasa suisting areas descrit		
		429.5	parking spaces	Same	Keep existing amendment		

		F		1			T
						Agree with	
						recommendations	
			05 General Buildin	g Heights an	d Areas		
TAG Member: Damen	Jeg						
	Section 503—General building				Amendment not needed;		
<u>51-50-0503</u>	height and area limitations.	503.1.4	Occupied roofs	Same	addressed by model code		
	Section 504—Building height		ALLOWABLE BUILDING HEIGHT		Keep existing amendment as		
<u>51-50-0504</u>	and number of stories.	Table 504.3	IN FEET ABOVE GRADE PLANE	Same	modified		Still need footnote i.
			ALLOWABLE NUMBER OF		Keep existing amendment as		
		Table 504.4	STORIES ABOVE GRADE PLANE	Same	modified		Still need footnote i
			Stair enclosure pressurization	_			
		504.4.1	increase	Same	Keep state amendment		
			ALLOWARIE AREA FACTOR (A)				
			ALLOWABLE AREA FACTOR (At		A		
	s .: 505 B !!!!	T 11 5000	= NS, S1, S13R, S13D or SM, as		Amendment not needed;		
<u>51-50-0506</u>	Section 506—Building area.	Table 506.2	applicable) IN SQUARE FEET	Same	addressed by model code		
54 50 0500	Section 508—Mixed use and	500 4 4 4			Amendment not needed;		
<u>51-50-0508</u>	occupancy.	508.4.4.1	Construction	Same	addressed by model code		
F4 F0 0F00	Continue 500 In side at all control	500 4 4 4	Type IV-B and IV-C	C	Amendment not needed;		
<u>51-50-0509</u>	Section 509—Incidental uses.	509.4.1.1	construction	Same	addressed by model code		Coordinate with NEC Section
		Table 509	INCIDENTAL USES	Table 509.1	Keep state amendment		450.21(B)
		Table 303	INCIDENTAL OSES	Table 303.1	Reep state amendment		430.21(B)
							Item 1 - not needed; Item 4 -
							not needed; Keep amendment
							in Item 5 (incorrectly shown as
	Section 510—Special		Horizontal building separation		Keep existing amendment as		Item 4 in WAC 51-50510).
51-50-0510	provisions.	510.2	allowance	Same	modified		Keep amendment in Item 6.
31 30 0310	provisions.	310.2	Group R-1 and R-2 buildings of	Sunc	Amendment not needed;		Reep differential territorio.
		510.5	Type IIIA construction	Same	addressed by model code		*typo in current code
			· ype ··································		and the second of the second	Approve	
						recommendations	
			06 Types of	Construction	1		
TAG Member: Todd Be	evreuther		00 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	Construction			
I AG IVIEIIIDEI: 1000 BE	eyreutilei			1			
			FIRE-RESISTANCE RATING				
			REQUIREMENTS FOR BUILDING				Discuss footnote c—Further
51-50-0601	Section 601—General.	Table 601	ELEMENTS (HOURS)	Same	Supersede with 2021		research is needed.
31 30 0001	Jedien de Generan		FIRE-RESISTANCE RATING	-3	- poisone marie ver		
			REQUIREMENTS FOR EXTERIOR				Table moved to 705.5, note in
	Section 602—Construction		WALLS BASED ON FIRE				Table 601 and in Table 601
51-50-0602	classification.	Table 602	SEPARATION DISTANCE	705.5	Delete in 602; keep in 705.5		footnote e
		602.4	Type IV	Same	Supersede with 2021		Addressed by model code
	<u> </u>	602.4.1	Type IV-A	Same	Supersede with 2021		Addressed by model code

		602.4.1.1	Exterior protection	Same	Supersede with 2021		Addressed by model code
		602.4.1.2	Interior protection	Same	Supersede with 2021		Addressed by model code
		602.4.1.2.1	Protection time	Same	Supersede with 2021		Addressed by model code
		602.4.1.3	Floors	Same	Supersede with 2021		Addressed by model code
		602.4.1.4	Roofs	Same	Supersede with 2021		Addressed by model code
		602.4.1.5	Concealed spaces	Same	Supersede with 2021		Addressed by model code
		602.4.1.6	Shafts	Same	Supersede with 2021		Addressed by model code
		602.4.2	Type IV-B	Same	Supersede with 2021		Addressed by model code
		602.4.2.1	Exterior protection	Same	Supersede with 2021		Addressed by model code
		602.4.2.2	Interior protection	Same	Supersede with 2021		Addressed by model code
		602.4.2.2.1	Protection time	Same	Supersede with 2021		Addressed by model code
		602.4.2.2.2	Protected area	Same	Supersede with 2021		Addressed by model code
		602.4.2.2.3	Mixed unprotected areas	Same	Supersede with 2021		Addressed by model code
			Separation distance between				
			unprotected mass timber				
		602.4.2.2.4	elements	Same	Supersede with 2021		Addressed by model code
		602.4.2.3	Floors	Same	Supersede with 2021		Addressed by model code
		602.4.2.4	Roofs	Same	Supersede with 2021		Addressed by model code
		602.4.2.5	Concealed spaces	Same	Supersede with 2021		Addressed by model code
		602.4.2.6	Shafts	Same	Supersede with 2021		Addressed by model code
		602.4.3	Type IV-C	Same	Supersede with 2021		Addressed by model code
		602.4.3.1	Exterior protection	Same	Supersede with 2021		Addressed by model code
		602.4.3.2	Interior protection	Same	Supersede with 2021		Addressed by model code
		602.4.3.3	Floors	Same	Supersede with 2021		Addressed by model code
					·		Title change reflects no interior
		602.4.3.4	Roofs	Same	Supersede with 2021		requirements.
		602.4.3.5	Concealed spaces	Same	Supersede with 2021		Addressed by model code
		602.4.3.6	Shafts	Same	Supersede with 2021		Addressed by model code
		602.4.4	Type IV-HT	Same	Supersede with 2021		Addressed by model code
			Fire-retardant-treated wood in	_			,
		602.4.4.1	exterior walls	Same	Supersede with 2021		Addressed by model code
			Cross-laminated timber in				, and a second of the second o
		602.4.4.2	exterior walls	Same	Supersede with 2021		Addressed by model code
		002111112	exterior trails	June	ouperseue man 2021		Note new section as it was
		N/A	Concealed spaces	602.4.4.3	Add with 2021 (no action)		outside of ICC TWB ad hoc
		14/75	concealed spaces	002.4.4.3	Add With 2021 (no detion)		outside of fee TWB dd floe
							Why isn't this in WA 2018? it
							appears in a IBC 2015/2018. Staff
		1					Comment: Sections 602.4.4.4 -
		missing	Exterior structural members	602.4.4.4	Add with 2021?		602.4.4.9 were deleted.
	Section 603—Combustible	iiiissiiig	Exterior structural members	502.4.4.4	Add With 2021!		552.4.4.5 Were deleted.
	material in Types I and II	1					Discuss 'approved connector' add
51-50-0603		603.1 (1.4)	Allowable materials	Same	Keen existing amondment		per 2304.10.5
31-30-0003	construction.	003.1 (1.4)	Allowable HidleHals	Saille	Keep existing amendment	Agree with	pei 2304.10.3
		1					
						recommendations	
					ATHICAC		
			07 Fire and Smoke	e Protection Fe	atures		
TAG Member: Will Rod	riguez		U/ Fire and Smoke	e Protection Fe	eatures		
TAG Member: Will Rod	riguez		Determination of	Protection Fe	eatures		
TAG Member: Will Rod	riguez Section 703—Fire-resistance			703.6	Amendment not needed;		

		1				
						The exception is worded slightly
						different in both the amendment
			Sealing of adjacent mass		Amendment not needed;	and model code but with same
		703.9	timber elements	703.7	addressed by model code.	intent.
					Keep amendment, there are	
					small wording differences that	
			Secondary (nonstructural)		should be reviewed further	
	Section 704—Fire-resistance		attachments to structural		between model code and	
51-50-0704	rating of structural members.	704.6.1	members	Same	amedment	
	Section 705—Exterior walls		Exterior walls and projections		Amendment not needed;	
51-50-0705	and projections.	705.1	shall comply with this section	Same	addressed by model code	Revise title to: General
31 30 0703	and projections.	703.1	Shan comply with this section	Same	dudiessed by model code	Nevise title to. General
					Keep amendment, model code	
					does not reflect entire	
					amendment. Missing	
				1_	exceptions and some wording	
		705.2	Projections	Same	model code from amendment.	
						The section in the model code is
						705.2.4 and not 705.2.5
						Staff Comment: Existing
					Amendment not needed;	amendment doesn't seem to be
		705.2.5	Projecting floors	Same	addressed by model code	addressed by the model code.
					Amendment not needed;	
<u>51-50-0706</u>	Section 706—Fire walls.	706.6.1	Stepped buildings	Same	addressed by model code	
						The model code adds a second
						exception not listed in the
					Amendment not needed;	amendment. The amendment
51-50-07070	Section 707—Fire barriers.	707.4	Exterior walls	Same	addressed by model code	only lists one exception.
<u>51-50-07070</u>	Section 707—Fire barriers.	707.4	Exterior walls	Same		offly fists offe exception.
		707.5		6	Amendment not needed;	
		707.5	Continuity	Same	addressed by model code	
					Amendment not needed;	
<u>51-50-0713</u>	Section 713—Shaft enclosures.	713.13.4	Chute discharge room	Same	addressed by model code	
			Chute venting and roof			
		713.13.7	termination	Same	Keep state amendment	
		1				There are exceptions on
	Section 716—Opening			1		amendment not found on model
51-50-0716	protectives.	716.2.6.1	Door closing	Same	Keep state amendment	code
	,			-		
		1				The model code contains two
	Section 717—Ducts and air	1			Amendment not needed;	new sections 3.1 and 3.2 not
51-50-0717		717.5.2	Fire barriers	Cama	-	
21-20-0/1/	transfer openings.	/1/.5.2	rife partiers	Same	addressed by model code	mentioned in the amendment.
						The wording in exception 4 is
		1				structured a little different than
		L			Amendment not needed;	in the amendment but containg
		717.5.4	Fire partitions	Same	addressed by model code	same content.

							The wording for item 8 is more
	Section 718—Concealed				Amendment not needed;		condenced in the amendment
<u>51-50-0718</u>	spaces.	718.2.1	Fireblocking materials	Same	addressed by model code		versus in the model code.
					Keep amendment, model code		Staff Comment: Re-evaluate the
					does not reflect the overall		new model code language and
					amendment. There are		section references. The
	Section 722—Calculated fire		Fire-resistance rating of mass		differences in the table and		differences may be due to model
<u>51-50-0722</u>	resistance.	722.7	timber	Same	section references.		code changes in other sections.
					Keep amendment, the		
					reference to section 703.6 in		
					the model code differs from		
					section 703.8 referenced in the		Staff Comment: The reference to
					amendment. Verify which		703.6 is correct due to the model
		722.7.1	Minimum required protection	Same	section number is correct.		code renumbering.
					Keep amendment, table		
					refenced in the model code		
			PROTECTION REQUIRED FROM		and amendment differ. Verify		
			NONCOMBUSTIBLE COVERING		which table references are		Staff Comment: Table references
		TABLE 722.7.1(1)	MATERIAL	Same	correct.		seem to match.
			PROTECTION PROVIDED BY				
			NONCOMBUSTIBLE COVERING		Amendment not needed;		
		TABLE 722.7.1(2)	MATERIAL	Same	addressed by model code		
		722 7 2	Installation of gypsum board	6	Amendment not needed;		
		722.7.2	noncombustible protection	Same	addressed by model code		
					Keep amendment, there are		
					some differences in the		
					standards referenced in the		
					exception. Model code references AISI S220 and		
		722 7 2 4	Interior confesso	Come	amendment references ASTM C645		
-		722.7.2.1	Interior surfaces	Same	Amendment not needed;		
		722.7.2.2	Exterior surfaces	Same	addressed by model code		
	+	1 44.1.4.4	LATERIOR SURFACES	Jaille	addressed by illouel code	Accept	
						recommendations	
			00.1-1			recommendations	
			us Interio	or Finishes			
TAG Member: Mark Sniffe	n	T	I	1		T	
							Further research may be needed
	s .:						on use of term "heavy timber"
54 50 0000	Section 803—Wall and ceiling	000.0		6	Amendment not needed;		rather than Type IVmass timber
<u>51-50-0803</u>	finishes.	803.3	Heavy timber exemption	Same	covered by model code		defined but not heavy timber
						Accept	
				l		recommendations	
			09 Fire Protection ar	nd Life Safety S	Systems		

AG Member: Corey	Thomas					Coordinate Chapter 9 with the IFC TAG
•	Section 903—Automatic					
51-50-0903	sprinkler systems.	903.2.1.8	Nightclub	Same	Keep state amendment	
	7		8 ****			Not in 2018 IBC; needs to be
		903.2.1.6	Assembly occupancies on roof	Same	Keep state amendment	copied over from the IFC.
		303.2.1.0	Assembly occupancies on root	Same	Reep state amenament	Reference to Table 1004.1.2
						needs to be changed to Table
		002.2.2	Grave F	C	Vt-t	_
		903.2.3	Group E	Same	Keep state amendment	1004.5 (3 locations)
		903.2.6	Group I	Same	Keep state amendment	
						Reference to Table 1004.1.2
						needs to be changed to Table
		903.2.6.1	Group I-4	Same	Keep state amendment	1004.5
					Amendment not needed;	
		903.2.7	Group M	Same	addressed by model code	
		903.2.8	Group R	Same	Keep state amendment	
			Group S-1 upholstered		Amendment not needed;	
		903.2.9.3	furniture and mattresses	903.2.9.4	addressed by model code	
		903.2.9.3	Turriture and mattresses	303.2.3.4	addressed by moder code	There is not a current state
			6 .6			
			Specific building areas and			amendment in this section;
		903.2.11	hazards	Same	Remove from review table	remove from WAC.
						Not in 2018 IBC; needs to be
		903.2.11.1.3	Basements	Same	Keep state amendment	copied over from the IFC.
			Relocatable buildings within			
		903.2.11.7	buildings	Same	Keep state amendment	
			Underground portions of fire			
			protection system water			
		903.3.5.3	supply piping	Same	Keep state amendment	
						This needs to be copied over
						from the IFC. Add the word,
						'NFPA 96' in the body of the coo
						•
						and add new Item 3. Automatic
					Correlate amendment with	water mist systems, NFPA 750.
		904.12	Commercial cooking systems.	904.13	new ICC language	Then re-number Items 4, 5 and 0
	Section 907—Fire alarm and					
<u>51-50-0907</u>	detection systems.	907.2.3	Group E	Same	Keep state amendment	
		907.2.3.1	Sprinkler systems or detection	Same	Keep state amendment	
						Not in 2018 IBC; needs to be
		907.2.6.1	Group I-1	Same	Keep state amendment	copied over from the IFC.
		907.2.6.4	Group I-4 occupancies	Same	Keep state amendment	
		237.12.01.				
						The base code did change here
						<u> </u>
						but not to what we have, not
						sure if the TAG would like to
		907.5.2.1.2	Maximum sound pressure	Same	Keep state amendment	review the new base code or no

			NICET: National Institute for				
			Certification in Engineering				
			Technologies and ESA/NTS:				Check the number, please no
			Electronic Security				there is no Section 907.9, so
			Association/National Training				maybe it should change or pu
		007.10		907.9	Kaan state amendment		, ,
		907.10 907.10.1			Keep state amendment		reserve on 907.9?
			'	907.9.1	Keep state amendment		
		907.10.2	-	907.9.2	Keep state amendment		
	5 11 222 5 1 1 1	907.10.3	Testing/maintenance	907.9.3	Keep state amendment		
	Section 909—Smoke control						
51-50-0909	systems.	909.21.12	Hoistway venting	Same	Keep state amendment		
		909.21.13	Machine rooms	Same	Keep state amendment		
			Pressurized stairways and				
		909.6.3	elevator hoistways.	Same	No current state amendment		
			1				Reference to Section 4.12.2.1
			Protection of fire pump rooms		Keep state amendment as		needs to be updated to Section
51-50-0913	Section 913—Fire pumps.	913.2.1	and access	Same	modified		4.14.2.1.2.
	Section 915—Carbon						
51-50-0915	monoxide detection.	915.1	General	Same	Keep state amendment		
		915.1.1	Where required	Same	Keep state amendment		
					Keep state amendment as		Update title of section to Fue
		915.1.3	Forced-air furnaces	Same	modified		Burning, Forced-air furnaces.
			Fuel-burning appliances				
			outside of dwelling units,				
		915.1.4	sleeping units and classrooms	Same	Keep state amendment		
		915.1.5	Private garages	Same	Keep state amendment		
		915.1.6	Exempt garages	Same	Keep state amendment		
		915.2.1	Dwelling units	Same	Keep state amendment		
		915.2.2	Sleeping units	Same	Keep state amendment		
		915.2.3	Group E occupancies	Same	Keep state amendment		
		+	+		<u> </u>	Agree with	
						recommendations	
			10 Means	s of Egress		recommendations	
			10 Mean	s of Egress		<u>recommendations</u>	Coordinate Chapter 10 with
G Member: Chris Se	eaman/ Al Spaulding		10 Mean	s of Egress		<u>recommendations</u>	Coordinate Chapter 10 with IFC TAG
G Member: Chris Se	eaman/ Al Spaulding		10 Means	s of Egress		recommendations	Coordinate Chapter 10 with IFC TAG Needs correlation not in the
G Member: Chris Se 51-50-1004	eaman/ Al Spaulding Section 1004—Occupant load.	Table 1004.5	MAXIMUM FLOOR AREA	s of Egress	Keep state amendment	recommendations	IFC TAG
		Table 1004.5	MAXIMUM FLOOR AREA		Keep state amendment	recommendations	IFC TAG Needs correlation not in th
			MAXIMUM FLOOR AREA			recommendations	IFC TAG Needs correlation not in th
	Section 1004—Occupant load.		MAXIMUM FLOOR AREA ALLOWANCE PER OCCUPANT		Keep state amendment No longer needed; addressed by model code	recommendations	IFC TAG Needs correlation not in th
<u>51-50-1004</u>	Section 1004—Occupant load. Section 1006—Number of exits		MAXIMUM FLOOR AREA ALLOWANCE PER OCCUPANT SPACES WITH ONE EXIT OR EXIT ACCESS DOORWAY	Same	No longer needed; addressed	recommendations	IFC TAG Needs correlation not in th
<u>51-50-1004</u>	Section 1004—Occupant load. Section 1006—Number of exits		MAXIMUM FLOOR AREA ALLOWANCE PER OCCUPANT SPACES WITH ONE EXIT OR EXIT ACCESS DOORWAY Egress based on occupant load	Same	No longer needed; addressed	recommendations	IFC TAG Needs correlation not in th
<u>51-50-1004</u>	Section 1004—Occupant load. Section 1006—Number of exits	Table 1006.2.1	MAXIMUM FLOOR AREA ALLOWANCE PER OCCUPANT SPACES WITH ONE EXIT OR EXIT ACCESS DOORWAY Egress based on occupant load and common path of egress	Same Same	No longer needed; addressed by model code	recommendations	IFC TAG Needs correlation not in th
<u>51-50-1004</u>	Section 1004—Occupant load. Section 1006—Number of exits		MAXIMUM FLOOR AREA ALLOWANCE PER OCCUPANT SPACES WITH ONE EXIT OR EXIT ACCESS DOORWAY Egress based on occupant load and common path of egress	Same	No longer needed; addressed	recommendations	IFC TAG Needs correlation not in th fire code
<u>51-50-1004</u>	Section 1004—Occupant load. Section 1006—Number of exits	Table 1006.2.1	MAXIMUM FLOOR AREA ALLOWANCE PER OCCUPANT SPACES WITH ONE EXIT OR EXIT ACCESS DOORWAY Egress based on occupant load and common path of egress	Same Same	No longer needed; addressed by model code	recommendations	IFC TAG Needs correlation not in th fire code
<u>51-50-1004</u>	Section 1004—Occupant load. Section 1006—Number of exits	Table 1006.2.1	MAXIMUM FLOOR AREA ALLOWANCE PER OCCUPANT SPACES WITH ONE EXIT OR EXIT ACCESS DOORWAY Egress based on occupant load and common path of egress	Same Same	No longer needed; addressed by model code	recommendations	Not in fire code Not in fire existing State Stat
<u>51-50-1004</u>	Section 1004—Occupant load. Section 1006—Number of exits	Table 1006.2.1	MAXIMUM FLOOR AREA ALLOWANCE PER OCCUPANT SPACES WITH ONE EXIT OR EXIT ACCESS DOORWAY Egress based on occupant load and common path of egress	Same Same	No longer needed; addressed by model code	recommendations	Needs correlation not in the fire code Not in fire code Sta Comment: The existing amendment shows that Sect
<u>51-50-1004</u>	Section 1004—Occupant load. Section 1006—Number of exits	Table 1006.2.1	MAXIMUM FLOOR AREA ALLOWANCE PER OCCUPANT SPACES WITH ONE EXIT OR EXIT ACCESS DOORWAY Egress based on occupant load and common path of egress	Same Same	No longer needed; addressed by model code	recommendations	IFC TAG Needs correlation not in th fire code Not in fire code Star

		1	T			1
						Not in fire code Staff
						Comment: The existing
						amebndment and the new
						section in 2021 IBC have the
						same regulatory effect. New
						Section 1006.2.2.4 refers to
						NFPA70 Articles 110.26 and
						110.33 for electrical equipment
						rated 1,000 volts or less, and
						more than 1,000 volts. The
						existing amendment in
						1006.2.2.7 provides the same
						requirements, but it is more
						specific, using language from
					Needs further research, new	NFPA 70, Articles 110.26 and
		1006.2.2.7	Electrical equipment rooms	1006.2.2.4	language in 2021	110.33.
					No longer needed; addressed	
		1006.3.3	Single exits	1006.3.4	by model code	
			STORIES WITH ONE EXIT OR			
			ACCESS TO ONE EXIT FOR R-2		No longer needed; addressed	
		Table 1006.3.3(1)	OCCUPANCIES	1006.3.4(1)	by model code	
		,	STORIES WITH ONE EXIT OR	,		
			ACCESS TO ONE EXIT FOR		No longer needed; addressed	
		Table 1006 3 3/3)	OTHER OCCUPANCIES	1006.3.4(2)	by model code	
	Section 1008—Means of	14510 1000.3.3(2)	OTTER OCCOT AIVELES	1000.3.4(2)	by model code	Reserved in fire codeNeed to
51-50-1008	egress illumination.	1008.2.3	Exit discharge	Same	Keep state amendment	correlate
31-30-1008	Section 1009—Accessible	1006.2.3	Accessible means of egress	Same	Reep state amendment	correlate
51-50-1009	means of egress.	1009.1	required	Same	Keep state amendment	
31-30-1003	ineans of egress.	1003.1	required	Jame	No longer needed; addressed	
		1009.2.1	Elevators required	Como		
		1009.2.1		Same Same	by model code	
		1009.8	Two-way communication	Same	Keep state amendment Need to correlate state	
		1000 0 1			amendment with new 2021	
		1009.8.1	System requirements	Same	language	
					Need to correlate state	Missing language in condition 7
	Section 1010—Doors, gates,				amendment with new 2021	needs to go with residential
<u>51-50-10100</u>	and turnstiles.	1010.1.9.4	Locks and latches	1010.2.4	language	treatment facilities as well
					Need to correlate state	
			Controlled egress doors in		amendment with new 2021	
		1010.1.9.7	Groups I-1 and I-2	1010.2.14	language	
					No longer needed; addressed	
		1010.1.10	Panic and fire exit hardware	1010.2.9	by model code	
			Electrical rooms and working			
		1010.1.10.3	clearances	1010.2.2.4.1	Keep state amendment	
					No longer needed; addressed	
<u>51-50-1011</u>	Section 1011—Stairways.	1011.7	Stairway construction	Same	by model code	
			Stairways in individual dwelling			
		1011.17	units	Same	Keep state amendment	
51-50-1012	Section 1012—Ramps.	1012.1	Scope	Same	Keep state amendment	1

							Not in fire code; Intent of state amendment? Staff
					Need to correlate state		Comment: New 2021 language
	Section 1019—Exit access		Occupancies other than		amendment with new 2021		looks the same as the existing
<u>51-50-1019</u>	stairways and ramps.	1019.3	Groups I-2 and I-3	Same	language		amendment.
					No longer needed; addressed		
<u>51-50-1020</u>	Section 1020—Corridors.	1020.4	Dead ends	1020.5	by model code		
					Need to correlate state		
					amendment with new 2021		
		1020.5	Air movement in corridors	1020.6	language		Not in fire code
	Section 1023—Interior exit				No longer needed; addressed		
<u>51-50-1023</u>	stairways and ramps.	1023.2	Construction	Same	by model code		
					No longer needed; addressed		
		1023.5	Penetrations	Same	by model code		
		1023.11	Smokeproof enclosures	1023.12	Keep state amendment		Not in fire code
	Section 1024—Exit				No longer needed; addressed		
51-50-10240	passageways.	1024.9	Exit passageway exterior walls	1024.8	by model code		
							Intent of amendment? May not be needed; Not in fire code. Staff Comment: Existing amendment was adopted to align
					Need to correlate state		IBC with IRC. The model code
	Section 1030—Emergency				amendment with new 2021		language in 2021 IRC and 2021
<u>51-50-10300</u>	escape and rescue.	1030.6	Drainage	1031.5.3	language		IBC is the same.
<u>51-50-10300</u>	escape and rescue.	1030.6	Drainage	1031.5.3	language	Agree with	IBC is the same.
51-50-10300	escape and rescue.	1030.6	Drainage	1031.5.3	language	Agree with recommendations	IBC is the same.
		1030.6		essibility	language	_	
51-50-10300 FAG Member: Stoyan 51-50-1101		1101.2			language Keep state amendment	_	Correct numbering in WAC
「AG Member: Stoyan	Bumbalov		11 Acc	essibility Same		recommendations	
「AG Member: Stoyan	Bumbalov	1101.2	Design (ICC A117.1 Section 403.5)	essibility Same	Keep state amendment Repeal the existing WA amendment and adopt the more restrictive requirement in ANSI	recommendations	Existing amendment for accessible route 44" width; 48" in ANSI.
「AG Member: Stoyan	Bumbalov	1101.2	Design (ICC A117.1 Section 403.5) Clear width of accessible route	essibility Same	Keep state amendment Repeal the existing WA amendment and adopt the more restrictive requirement in ANSI Keep the existing amendment	recommendations	Existing amendment for accessible route 44" width; 48" in ANSI. New language in ANSI requires
「AG Member: Stoyan	Bumbalov	1101.2	Design (ICC A117.1 Section 403.5) Clear width of accessible route (ICC A117.1 Section 404.2.8)	essibility Same Same	Keep state amendment Repeal the existing WA amendment and adopt the more restrictive requirement in ANSI Keep the existing amendment as modified to align with	recommendations	Existing amendment for accessible route 44" width; 48" in ANSI. New language in ANSI requires modification to the existing
「AG Member: Stoyan	Bumbalov	1101.2	Design (ICC A117.1 Section 403.5) Clear width of accessible route (ICC A117.1 Section 404.2.8) Door-opening force	essibility Same	Keep state amendment Repeal the existing WA amendment and adopt the more restrictive requirement in ANSI Keep the existing amendment	recommendations	Existing amendment for accessible route 44" width; 48" in ANSI. New language in ANSI requires
「AG Member: Stoyan	Bumbalov	1101.2	Design (ICC A117.1 Section 403.5) Clear width of accessible route (ICC A117.1 Section 404.2.8) Door-opening force (ICC A117.1 Section	essibility Same Same	Keep state amendment Repeal the existing WA amendment and adopt the more restrictive requirement in ANSI Keep the existing amendment as modified to align with changes to 2017 ANSI	recommendations	Existing amendment for accessible route 44" width; 48" in ANSI. New language in ANSI requires modification to the existing amendment.
「AG Member: Stoyan	Bumbalov	1101.2.1	Design (ICC A117.1 Section 403.5) Clear width of accessible route (ICC A117.1 Section 404.2.8) Door-opening force (ICC A117.1 Section 404.2.8) Arrangement of	Same Same	Keep state amendment Repeal the existing WA amendment and adopt the more restrictive requirement in ANSI Keep the existing amendment as modified to align with changes to 2017 ANSI Existing amendment is not	recommendations	Existing amendment for accessible route 44" width; 48" in ANSI. New language in ANSI requires modification to the existing amendment. The same language appears in
「AG Member: Stoyan	Bumbalov	1101.2	Design (ICC A117.1 Section 403.5) Clear width of accessible route (ICC A117.1 Section 404.2.8) Door-opening force (ICC A117.1 Section	essibility Same Same	Keep state amendment Repeal the existing WA amendment and adopt the more restrictive requirement in ANSI Keep the existing amendment as modified to align with changes to 2017 ANSI Existing amendment is not needed	recommendations	Existing amendment for accessible route 44" width; 48" in ANSI. New language in ANSI requires modification to the existing amendment.
「AG Member: Stoyan	Bumbalov	1101.2.1	Design (ICC A117.1 Section 403.5) Clear width of accessible route (ICC A117.1 Section 404.2.8) Door-opening force (ICC A117.1 Section 404.2.8) Arrangement of	Same Same	Keep state amendment Repeal the existing WA amendment and adopt the more restrictive requirement in ANSI Keep the existing amendment as modified to align with changes to 2017 ANSI Existing amendment is not needed Keep existing amendment as	recommendations	Existing amendment for accessible route 44" width; 48" in ANSI. New language in ANSI requires modification to the existing amendment. The same language appears in
「AG Member: Stoyan	Bumbalov	1101.2.1	Design (ICC A117.1 Section 403.5) Clear width of accessible route (ICC A117.1 Section 404.2.8) Door-opening force (ICC A117.1 Section 404.2.8) A7.4.6.2.2) Arrangement of elevator car buttons	Same Same	Keep state amendment Repeal the existing WA amendment and adopt the more restrictive requirement in ANSI Keep the existing amendment as modified to align with changes to 2017 ANSI Existing amendment is not needed Keep existing amendment as modified. The applicable	recommendations	Existing amendment for accessible route 44" width; 48" in ANSI. New language in ANSI requires modification to the existing amendment. The same language appears in ANSI
「AG Member: Stoyan	Bumbalov	1101.2.1 1101.2.1 1101.2.2	Design (ICC A117.1 Section 403.5) Clear width of accessible route (ICC A117.1 Section 404.2.8) Door-opening force (ICC A117.1 Section 404.2.2) Arrangement of elevator car buttons (ICC ANSI A117.1 606.7)	Same Same Same	Keep state amendment Repeal the existing WA amendment and adopt the more restrictive requirement in ANSI Keep the existing amendment as modified to align with changes to 2017 ANSI Existing amendment is not needed Keep existing amendment as modified. The applicable section in ANSI is 603.6; not	recommendations	Existing amendment for accessible route 44" width; 48" in ANSI. New language in ANSI requires modification to the existing amendment. The same language appears in ANSI
「AG Member: Stoyan	Bumbalov	1101.2.1	Design (ICC A117.1 Section 403.5) Clear width of accessible route (ICC A117.1 Section 404.2.8) Door-opening force (ICC A117.1 Section 404.2.2) Arrangement of elevator car buttons (ICC ANSI A117.1 606.7) Operable parts	Same Same	Keep state amendment Repeal the existing WA amendment and adopt the more restrictive requirement in ANSI Keep the existing amendment as modified to align with changes to 2017 ANSI Existing amendment is not needed Keep existing amendment as modified. The applicable	recommendations	Existing amendment for accessible route 44" width; 48" in ANSI. New language in ANSI requires modification to the existing amendment. The same language appears in ANSI
「AG Member: Stoyan	Bumbalov	1101.2.1 1101.2.1 1101.2.2	Design (ICC A117.1 Section 403.5) Clear width of accessible route (ICC A117.1 Section 404.2.8) Door-opening force (ICC A117.1 Section 404.2.8) A07.4.6.2.2) Arrangement of elevator car buttons (ICC ANSI A117.1 606.7) Operable parts (ICC A117.1 Section 604.6)	Same Same Same	Keep state amendment Repeal the existing WA amendment and adopt the more restrictive requirement in ANSI Keep the existing amendment as modified to align with changes to 2017 ANSI Existing amendment is not needed Keep existing amendment as modified. The applicable section in ANSI is 603.6; not	recommendations	Existing amendment for accessible route 44" width; 48" in ANSI. New language in ANSI requires modification to the existing amendment. The same language appears in ANSI
「AG Member: Stoyan	Bumbalov	1101.2.1 1101.2.1 1101.2.2	Design (ICC A117.1 Section 403.5) Clear width of accessible route (ICC A117.1 Section 404.2.8) Door-opening force (ICC A117.1 Section 404.2.8) A07.4.6.2.2) Arrangement of elevator car buttons (ICC ANSI A117.1 606.7) Operable parts (ICC A117.1 Section 604.6) Flush controls	Same Same Same	Keep state amendment Repeal the existing WA amendment and adopt the more restrictive requirement in ANSI Keep the existing amendment as modified to align with changes to 2017 ANSI Existing amendment is not needed Keep existing amendment as modified. The applicable section in ANSI is 603.6; not	recommendations	Existing amendment for accessible route 44" width; 48" in ANSI. New language in ANSI requires modification to the existing amendment. The same language appears in ANSI
「AG Member: Stoyan	Bumbalov	1101.2.1 1101.2.1 1101.2.2 1101.2.3	Design (ICC A117.1 Section 403.5) Clear width of accessible route (ICC A117.1 Section 404.2.8) Door-opening force (ICC A117.1 Section 404.2.8) A07.4.6.2.2) Arrangement of elevator car buttons (ICC ANSI A117.1 606.7) Operable parts (ICC A117.1 Section 604.6)	Same Same Same	Keep state amendment Repeal the existing WA amendment and adopt the more restrictive requirement in ANSI Keep the existing amendment as modified to align with changes to 2017 ANSI Existing amendment is not needed Keep existing amendment as modified. The applicable section in ANSI is 603.6; not 606.7	recommendations	Existing amendment for accessible route 44" width; 48" in ANSI. New language in ANSI requires modification to the existing amendment. The same language appears in ANSI
「AG Member: Stoyan	Bumbalov	1101.2.1 1101.2.1 1101.2.2 1101.2.3	Design (ICC A117.1 Section 403.5) Clear width of accessible route (ICC A117.1 Section 404.2.8) Door-opening force (ICC A117.1 Section 404.2.8) A07.4.6.2.2) Arrangement of elevator car buttons (ICC ANSI A117.1 606.7) Operable parts (ICC A117.1 Section 604.6) Flush controls	Same Same Same	Keep state amendment Repeal the existing WA amendment and adopt the more restrictive requirement in ANSI Keep the existing amendment as modified to align with changes to 2017 ANSI Existing amendment is not needed Keep existing amendment as modified. The applicable section in ANSI is 603.6; not 606.7	recommendations	Existing amendment for accessible route 44" width; 48" in ANSI. New language in ANSI requires modification to the existing amendment. The same language appears in ANSI

			(ICC A117.1 Section 502.2)			
		1101.2.7	Vehicle space size	Same	Keep existing amendment	
		1101111	(ICC A117.1 Section 502.4.2)	oue	neep existing amenaniene	
		1101.2.8	Access aisle width	Same	Keep existing amendment	
		1101.2.0	(ICC A117.1 Section 502.7)	Junic	Recep existing amendment	
		1101.2.9	Identification	Same	Keep existing amendment	
		1101.2.9	identification	Same	Repeal existing amendment;	
	Section 1105—Accessible				addressed by model code	
E4 E0 440E0		1105 1 0	A	1105 1 1	•	
<u>51-50-11050</u>	entrances.	1105.1.8	Automatic doors	1105.1.1	Section 1105.1.1.	
			DUDUIC ENTRANCE MUTU		Repeal existing amendment;	
		T 11 4405 4 0	PUBLIC ENTRANCE WITH	T 11 4405 4 4	addressed by model code	
	1 1100 0 11	Table 1105.1.8	POWER-OPERATED DOORS	Table 1105.1.1	Table 1105.1.1.	
	Section 1106—Parking and		l		Keep existing amendment;	"
<u>51-50-1106</u>	passenger loading facilities.	1106.6	Location	1106.7	renumber to 1106.7.	Modify WAC numbering
					Repeal existing amendment;	
	Section 1107—Dwelling units				addressed by model code	
<u>51-50-1107</u>	and sleeping units.	1107.5.1	Group 1	1108.5.1	Section 1108.5.1.	Modify WAC numbering
						The model code section adds nev
					Existing amendment not	requirements for the accessible
			Accessible units in Group I-1,		needed; addressed by model	units to be dispersed among the
		1107.5.1.1	Condition 1	1108.5.1.1	code Section 1108.5.1.1.	various classes of units.
						The model code section adds nev
					Existing amendment not	requirements for the accessible
			Accessible units in Group I-1,		needed; addressed by model	units to be dispersed among the
		1107.5.1.2	Condition 2	1108.5.1.2	code Section 1108.5.1.2.	various classes of units.
					Existing amendment not	
					needed; addressed by model	
		1107.5.1.3	Type B units	1108.5.1.3	code Section 1108.5.1.3.	
		1107101110	. ype 5 ames	1100.5.1.0	Existing amendment not	
					needed; addressed by model	
		1107.5.2	Group I-2 nursing homes	1108.5.2	code Section 1108.5.2.	
		1107.3.2	Group 1-2 murshing mornes	1100.3.2	Existing amendment not	
					needed; addressed by model	
		1107.5.2.1	Accessible units	1108.5.2.1	code Section 1108.5.2.1.	
		1107.5.2.1	Accessible utilits	1100.3.2.1		+
			Croup I 2 robabilitation		Existing amendment not	
		1107 5 4	Group I-2 rehabilitation	1100 5 4	needed; addressed by model	
		1107.5.4	facilities	1108.5.4	code Section 1108.5.4	+
		1107 6 2 2 1		1100 6 3 3 1	Keep existing amendment;	
		1107.6.2.2.1	Type A units	1108.6.2.2.1	renumber to 1108.6.2.2.1.	
			Group R-2 other than live/work		Existing amendment not	
			units, apartment houses,		needed; addressed by model	
		1107.6.2.3	monasteries and convents	1108.6.2.3	code Section 1108.6.2.3	
					Existing amendment not	
	Section 1109—Other features				needed; addressed by model	
51-50-11090	and facilities.	1109.2	Toilet and bathing facilities	1110.2	code Section 1110.2.	Modify WAC numbering

	1	1		ı	
			Existing amendment not		
	Water closets designed for		needed; addressed by model		
1109.2.2	assisted toileting	1110.2.2	code Section 1110.2.2		
			Existing amendment not		
			needed; addressed by model		
1109.2.2.1	Location	1110.2.2.1	code Section 1110.2.2.1		
			Existing amendment not		
			needed; addressed by model		
1109.2.2.2	Clearance	1110.2.2.2	code Section 1110.2.2.2		
		-	Existing amendment not		
			needed; addressed by model		
1109.2.2.2.1	Clearance width	1110.2.2.2.1	code Section 1110.2.2.2.1		
			Existing amendment not		
			needed; addressed by model		
1109.2.2.2.2	Clearance depth	1110.2.2.2.2	code Section 1110.2.2.2.2		
			Existing amendment not		
			needed; addressed by model		
1109.2.2.2.3	Clearance overlap	1110.2.2.2.3	code Section 1110.2.2.2.3		
1100.2.2.2.3	Cicaranice overlap	1110.2.2.2.3	Existing amendment not		
			needed; addressed by model		
1109.2.2.3	Height	1110.2.2.3	code Section 1110.2.2.3		
1103.2.2.3	Height	1110.2.2.3	Existing amendment not		
			needed; addressed by model		
1109.2.2.4	Swing up grab bars	1110.2.2.4	code Section 1110.2.2.4		
1109.2.2.4	Swing-up grab bars	1110.2.2.4	Existing amendment not		
			needed; addressed by model		
1109.2.2.5	Flush controls	1110.2.2.5	code Section 1110.2.2.5		
1109.2.2.5	Flush controls	1110.2.2.5	Existing amendment not		
			needed; addressed by model		
1100 2 2 6	Diamanaga	1110 2 2 6			
 1109.2.2.6	Dispensers	1110.2.2.6	code Section 1110.2.2.6		
	Standard roll-in-type shower		Existing amendment not		
1100 3 3	compartment designed for	1110 2 2	needed; addressed by model		
1109.2.3	assisted bathing	1110.2.3	code Section 1110.2.3		
			Existing amendment not		
1100 2 2 1	Si	1110 2 2 1	needed; addressed by model		
1109.2.3.1	Size	1110.2.3.1	code Section 1110.2.3.1		
			Existing amendment not		
			needed; addressed by model		
1109.2.3.2	Clearance	1110.2.3.2	code Section 1110.2.3.2		
			Existing amendment not		
			needed; addressed by model		
1109.2.3.3	Grab bars	1110.2.3.3	code Section 1110.2.3.3		
			Existing amendment not		
			needed; addressed by model		
1109.2.3.3.1	Back-wall grab bar	1110.2.3.3.1	code Section 1110.2.3.3.1		
			Existing amendment not		
			needed; addressed by model		
1109.2.3.3.2	Side-wall grab bars	1110.2.3.3.2	code Section 1110.2.3.3.2		

					Existing amendment not	
					needed; addressed by model	
		1109.2.3.4	Soats	1110 2 2 4	code Section 1110.2.3.4	
		1109.2.5.4	Seats	1110.2.3.4		
					Existing amendment not	
					needed; addressed by model	
		1109.2.3.5	Controls and hand showers	1110.2.3.5	code Section 1110.2.3.5	
					Existing amendment not	
					needed; addressed by model	
		1109.2.3.6	Hand showers	1110.2.3.6	code Section 1110.2.3.6	
					Existing amendment not	
					needed; addressed by model	
		1109.2.3.7	Thresholds	1110.2.3.7	code Section 1110.2.3.7	
					Existing amendment not	
					needed; addressed by model	
		1109.2.3.8	Shower enclosures	1110.2.3.8	code Section 1110.2.3.8	
		1103.2.3.6	Shower enclosures	1110.2.3.8	Existing amendment not	
					•	
					needed; addressed by model	
		1109.2.3.9	Water temperature	1110.2.3.9	code Section 1110.2.3.9	
					Keep existing amendment;	
		1109.5.1	Minimum number	1110.5.1	renumber to 1110.5.1	
			12 Interior I	mprovements		
TAG Member: Sue Co	.ffm.on		12	p. o v ccc.		
TAG Member: Sue Co	iiiiaii			I	A	T
	s .: 4202 .V .:! .:	4202.4			Amendment not needed,	
<u>51-50-1202</u>	Section 1202—Ventilation.	1202.1	General	Same	covered by model code	
		1202.2	Attic spaces	1202.2.1	Keep state amendment	
						Look at possible integration of
		1202.4	Under-floor ventilation	Same	Keep state amendment	additional exceptions in IBC.
		1202.5	Natural ventilation	Same	Keep state amendment	
						Check internal section numbers
						throughout sectionmake sure
			Radon resistive construction			they are 1202.7.xx rather than
		1202.7		Same	Keep state amendment	1202.6
			standards	Same Same	Keep state amendment	T
		1202.7.1	standards Application	Same	Keep state amendment	1202.6
		1202.7.1 1202.7.1.1	standards Application No title	Same Same	Keep state amendment Keep state amendment	1202.6 Title subsection
		1202.7.1	standards Application	Same	Keep state amendment	1202.6
		1202.7.1 1202.7.1.1 1202.7.1.2	standards Application No title No title	Same Same Same	Keep state amendment Keep state amendment Keep state amendment	1202.6 Title subsection
		1202.7.1 1202.7.1.1 1202.7.1.2	standards Application No title No title State wide radon requirements	Same Same Same	Keep state amendment Keep state amendment Keep state amendment Keep state amendment	1202.6 Title subsection
		1202.7.1 1202.7.1.1 1202.7.1.2 1202.7.2 1202.7.2	standards Application No title No title State wide radon requirements Crawlspaces	Same Same Same Same	Keep state amendment	1202.6 Title subsection
		1202.7.1 1202.7.1.1 1202.7.1.2 1202.7.2 1202.7.2 1202.7.21 1202.7.2.2	standards Application No title No title State wide radon requirements Crawlspaces Ventilation	Same Same Same Same Same Same	Keep state amendment	1202.6 Title subsection
		1202.7.1 1202.7.1.1 1202.7.1.2 1202.7.2 1202.7.2	standards Application No title No title State wide radon requirements Crawlspaces Ventilation Crawlspace plenum systems	Same Same Same Same	Keep state amendment	1202.6 Title subsection
		1202.7.1 1202.7.1.1 1202.7.1.2 1202.7.2 1202.7.2 1202.7.21 1202.7.2.2 1202.7.2.3	standards Application No title No title State wide radon requirements Crawlspaces Ventilation	Same Same Same Same Same Same	Keep state amendment	1202.6 Title subsection
		1202.7.1 1202.7.1.1 1202.7.1.2 1202.7.2 1202.7.2 1202.7.2.1 1202.7.2.2 1202.7.2.3 1202.7.3	standards Application No title No title State wide radon requirements Crawlspaces Ventilation Crawlspace plenum systems	Same Same Same Same Same Same	Keep state amendment	1202.6 Title subsection
		1202.7.1 1202.7.1.1 1202.7.1.2 1202.7.2 1202.7.2 1202.7.21 1202.7.2.2 1202.7.2.3	standards Application No title No title State wide radon requirements Crawlspaces Ventilation Crawlspace plenum systems Radon prescriptive	Same Same Same Same Same Same Same	Keep state amendment	1202.6 Title subsection
		1202.7.1 1202.7.1.1 1202.7.1.2 1202.7.2 1202.7.2 1202.7.2.1 1202.7.2.2 1202.7.2.3 1202.7.3	standards Application No title No title State wide radon requirements Crawlspaces Ventilation Crawlspace plenum systems Radon prescriptive requirements	Same Same Same Same Same Same Same Same	Keep state amendment	1202.6 Title subsection
		1202.7.1 1202.7.1.1 1202.7.1.2 1202.7.2 1202.7.2 1202.7.2.1 1202.7.2.2 1202.7.2.3 1202.7.3	standards Application No title No title State wide radon requirements Crawlspaces Ventilation Crawlspace plenum systems Radon prescriptive requirements	Same Same Same Same Same Same Same Same	Keep state amendment	1202.6 Title subsection
		1202.7.1 1202.7.1.1 1202.7.1.2 1202.7.2 1202.7.2 1202.7.2.1 1202.7.2.2 1202.7.2.3 1202.7.3 1202.7.3.1	standards Application No title No title State wide radon requirements Crawlspaces Ventilation Crawlspace plenum systems Radon prescriptive requirements Scope Floors in contact with the earth	Same Same Same Same Same Same Same Same	Keep state amendment	1202.6 Title subsection
		1202.7.1 1202.7.1.1 1202.7.1.2 1202.7.2 1202.7.2.1 1202.7.2.2 1202.7.2.3 1202.7.3.1 1202.7.3.1 1202.7.3.2 1202.7.3.2.1	standards Application No title No title State wide radon requirements Crawlspaces Ventilation Crawlspace plenum systems Radon prescriptive requirements Scope Floors in contact with the earth General	Same Same Same Same Same Same Same Same	Keep state amendment	1202.6 Title subsection
		1202.7.1 1202.7.1.1 1202.7.1.2 1202.7.2 1202.7.2.1 1202.7.2.2 1202.7.2.3 1202.7.3.1 1202.7.3.1 1202.7.3.2 1202.7.3.2.1 1202.7.3.2.1	standards Application No title No title State wide radon requirements Crawlspaces Ventilation Crawlspace plenum systems Radon prescriptive requirements Scope Floors in contact with the earth General Aggregate	Same Same Same Same Same Same Same Same	Keep state amendment	1202.6 Title subsection
		1202.7.1 1202.7.1.1 1202.7.1.2 1202.7.2 1202.7.2.1 1202.7.2.2 1202.7.2.3 1202.7.3.1 1202.7.3.1 1202.7.3.2 1202.7.3.2.1	standards Application No title No title State wide radon requirements Crawlspaces Ventilation Crawlspace plenum systems Radon prescriptive requirements Scope Floors in contact with the earth General	Same Same Same Same Same Same Same Same	Keep state amendment	1202.6 Title subsection

			Sealing of penetrations and				
		1202.7.3.2.5	ioints	Same	Keep state amendment		
		1202.7.3.2.6	Radon vent	Same	Keep state amendment		
			Fan circuit and wiring and				
		1202.7.3.2.7	location	Same	Keep state amendment		
		1202.7.3.2.8	Separate aggregate areas	Same	Keep state amendment		
		1202.7.3.2.9	Concrete block walls	Same	Keep state amendment		
	Section 1203—Temperature	120217101210	Contracte Stock Walls	ourre .	neep state amenament		
51-50-1203	control.	1203.1	Equipment and systems	Same	Keep state amendment		
<u>51 50 1205</u>	Control.	1203.1	Equipment and systems	Surric	Reep state amenament		Do not move to Chapter 2on
		1203.2	Definitions	Same	Keep state amendment		apply within this section
		1203.2	Primary heating source	Same	Keep state amendment		apply within this section
		1203.4	Solid fuel burning devices	Same	Keep state amendment		
	Section 1206—Sound	1203.4	John ruer burning devices	Same	Amendment not needed,		
F1 F0 130C	transmission.	1206.1	Scono	Same	covered by model code		
<u>51-50-1206</u>	transmission.	1200.1	Scope	Same	,		
	Cartian 1207 Interior				Amendment not needed,		
E4 E0 4207	Section 1207—Interior space	1207.4	Efficiency describe	1208 4	covered by model code with		Madifu MAC mount
<u>51-50-1207</u>	dimensions.	1207.4	Efficiency dwelling units	1208.4	greater detail		Modify WAC numbering
	Section 1209—Toilet and	1200 2 1		1210 2 1			
<u>51-50-1209</u>	bathroom requirements.	1209.3.1	Water closet compartment	1210.3.1	Keep state amendment		Modify WAC numbering
		1209.3.2	Urinal partitions	1210.3.2	Keep state amendment		Modify WAC numbering
						Accept Recommendation	
		*					
			13 Energy	y Efficiency			
AG Member: Damen J	eg		13 Energ	y Efficiency			
AG Member: Damen J	eg	Τ	13 Energ	y Efficiency			None
AG Member: Damen J	eg		_				None
			_	y Efficiency rior Walls			None
AG Member: Damen Jo AG Member: Chris Sea	ıman		_				None
	i man Section 1403		_				None
AG Member: Chris Sea	Section 1403- 1402—Performance	4400.2	14 Exte	rior Walls			
	Section 1403- 1402—Performance requirements.	1402.2	_		Keep state amendment		None Modify WAC numbering
AG Member: Chris Sea	Section 1403- 1402—Performance requirements. Section 1406—Combustible	1402.2	14 Exte	rior Walls	Need to move to 1405.2 but no		
AG Member: Chris Sea 51-50-1403	Section 1403- 1402—Performance requirements. Section 1406—Combustible materials on the exterior sides		14 Extermal Weather protection Balconies and similar	rior Walls	Need to move to 1405.2 but no change otherwise; also		Modify WAC numbering
AG Member: Chris Sea	Section 1403- 1402—Performance requirements. Section 1406—Combustible	1402.2	14 Exte	rior Walls	Need to move to 1405.2 but no		
AG Member: Chris Sea 51-50-1403	Section 1403- 1402—Performance requirements. Section 1406—Combustible materials on the exterior sides		14 Extermal Weather protection Balconies and similar	rior Walls	Need to move to 1405.2 but no change otherwise; also		Modify WAC numbering
AG Member: Chris Sea 51-50-1403	Section 1403- 1402—Performance requirements. Section 1406—Combustible materials on the exterior sides	1406.3	Weather protection Balconies and similar projections	rior Walls	Need to move to 1405.2 but no change otherwise; also		Modify WAC numbering
AG Member: Chris Sea 51-50-1403 51-50-1406	Section 1403- 1402—Performance requirements. Section 1406—Combustible materials on the exterior sides of exterior walls.		Weather protection Balconies and similar projections	rior Walls	Need to move to 1405.2 but no change otherwise; also		Modify WAC numbering
AG Member: Chris Sea 51-50-1403 51-50-1406	Section 1403- 1402—Performance requirements. Section 1406—Combustible materials on the exterior sides of exterior walls.	1406.3	Weather protection Balconies and similar projections	rior Walls	Need to move to 1405.2 but no change otherwise; also		Modify WAC numbering
AG Member: Chris Sea 51-50-1403 51-50-1406 5 Roof Assemblies and	Section 1403- 1402—Performance requirements. Section 1406—Combustible materials on the exterior sides of exterior walls.	1406.3	Weather protection Balconies and similar projections	rior Walls	Need to move to 1405.2 but no change otherwise; also		Modify WAC numbering
AG Member: Chris Sea 51-50-1403 51-50-1406 5 Roof Assemblies and	Section 1403- 1402—Performance requirements. Section 1406—Combustible materials on the exterior sides of exterior walls.	1406.3	Weather protection Balconies and similar projections	rior Walls	Need to move to 1405.2 but no change otherwise; also		Modify WAC numbering
AG Member: Chris Sea 51-50-1403 51-50-1406 5 Roof Assemblies and TAG Member:	Section 1403- 1402—Performance requirements. Section 1406—Combustible materials on the exterior sides of exterior walls.	1406.3 Group B Section	Weather protection Balconies and similar projections	rior Walls	Need to move to 1405.2 but no change otherwise; also		Modify WAC numbering
AG Member: Chris Sea 51-50-1403 51-50-1406 5 Roof Assemblies and TAG Member: 6 Structural Design	Section 1403- 1402—Performance requirements. Section 1406—Combustible materials on the exterior sides of exterior walls.	1406.3 Group B Section	Weather protection Balconies and similar projections	rior Walls	Need to move to 1405.2 but no change otherwise; also		Modify WAC numbering
AG Member: Chris Sea 51-50-1403 51-50-1406 5 Roof Assemblies and TAG Member: 6 Structural Design	Section 1403- 1402—Performance requirements. Section 1406—Combustible materials on the exterior sides of exterior walls. Rooftop Structures	1406.3 Group B Section	Weather protection Balconies and similar projections	rior Walls	Need to move to 1405.2 but no change otherwise; also		Modify WAC numbering
51-50-1406 5 Roof Assemblies and TAG Member: 6 Structural Design TAG Member:	Section 1403 1402—Performance requirements. Section 1406—Combustible materials on the exterior sides of exterior walls. Rooftop Structures Section 1604—General design	Group B Section Group B Section	Weather protection Balconies and similar projections RISK CATEGORY OF BUILDINGS	rior Walls	Need to move to 1405.2 but no change otherwise; also		Modify WAC numbering
AG Member: Chris Sea 51-50-1403 51-50-1406 5 Roof Assemblies and TAG Member: 6 Structural Design	Section 1403- 1402—Performance requirements. Section 1406—Combustible materials on the exterior sides of exterior walls. Rooftop Structures Section 1604—General design requirements	1406.3 Group B Section	Weather protection Balconies and similar projections	rior Walls	Need to move to 1405.2 but no change otherwise; also		Modify WAC numbering
AG Member: Chris Sea 51-50-1403 51-50-1406 6 Roof Assemblies and TAG Member: 6 Structural Design TAG Member: 51-50-1604	Section 1403- 1402—Performance requirements. Section 1406—Combustible materials on the exterior sides of exterior walls. Rooftop Structures Section 1604—General design requirements Section 1613—Earthquake	Group B Section Group B Section Table 1604.5	Weather protection Balconies and similar projections RISK CATEGORY OF BUILDINGS AND OTHER STRUCTURES	rior Walls	Need to move to 1405.2 but no change otherwise; also		Modify WAC numbering
AG Member: Chris Sea 51-50-1403 51-50-1406 6 Roof Assemblies and TAG Member: 6 Structural Design TAG Member:	Section 1403- 1402—Performance requirements. Section 1406—Combustible materials on the exterior sides of exterior walls. Rooftop Structures Section 1604—General design requirements	Group B Section Group B Section Table 1604.5	Weather protection Balconies and similar projections RISK CATEGORY OF BUILDINGS AND OTHER STRUCTURES Amendments to ASCE 7	rior Walls	Need to move to 1405.2 but no change otherwise; also		Modify WAC numbering
51-50-1406 Roof Assemblies and TAG Member: Structural Design TAG Member: 51-50-1604	Section 1403- 1402—Performance requirements. Section 1406—Combustible materials on the exterior sides of exterior walls. Rooftop Structures Section 1604—General design requirements Section 1613—Earthquake	Group B Section Group B Section Table 1604.5 1613.4 1613.4.1	Weather protection Balconies and similar projections RISK CATEGORY OF BUILDINGS AND OTHER STRUCTURES Amendments to ASCE 7 ASCE 7 Section 12.2.5.4	rior Walls	Need to move to 1405.2 but no change otherwise; also		Modify WAC numbering
AG Member: Chris Sea 51-50-1403 51-50-1406 5 Roof Assemblies and TAG Member: 5 Structural Design TAG Member: 51-50-1604	Section 1403- 1402—Performance requirements. Section 1406—Combustible materials on the exterior sides of exterior walls. Rooftop Structures Section 1604—General design requirements Section 1613—Earthquake	Group B Section Group B Section Table 1604.5	Weather protection Balconies and similar projections RISK CATEGORY OF BUILDINGS AND OTHER STRUCTURES Amendments to ASCE 7	rior Walls	Need to move to 1405.2 but no change otherwise; also		Modify WAC numbering

TAG Member:					
TAG WICHIDEL.					
	Casting 1705 Daming I				
F1 F0 1705	Section 1705—Required	1705 5 3	Naca timbou as a traction		
<u>51-50-1705</u>	special inspections and tests.	1705.5.3	Mass timber construction		
			REQUIRED SPECIAL		
			INSPECTIONS OF MASS		
		Table 1705.5.3	TIMBER CONSTRUCTION		
		1705.11.1	Structural wood		
		1705.12.2	Structural wood		
			Plumbing, mechanical and		
		1705.12.6	electrical components		
		1705.19	Sealing of mass timber		
			Exterior window and door		
<u>51-50-17090</u>	Preconstruction load tests.	1709.5	assemblies		
18 Soils and Foundations		Group B Section			
TAG Member:					
	Section 1807—Foundation				
	walls, retaining walls and				
<u>51-50-1807</u>	embedded posts and poles.	1807.2.2	Design lateral soil loads		
19 Concrete		Group B Section			
TAG Member:					
20 Aluminum		Group B Section			
TAG Member:					
21 Masonry		Group B Section			
TAG Member:					
	Section 2107—Allowable stress				
<u>51-50-21070</u>	design.	2107.1	General		
			TMS 402/ACI 530/ASCE 5,		
		2107.2	Section 2.1.8.7.1.1, lap splices		
	Section 2111—Masonry				
<u>51-50-2111</u>	fireplaces.	2111.8	Fireplaces		
		2111.8.1	Lintel and throat		
	Section 2115—Emission		Emission standards for factory-		
<u>51-50-2115</u>	standards.	2115.1	built fireplaces		
			Emission standards for		
			certified masonry and concrete		
		2115.2	fireplaces		
22 Steel		Group B Section			
TAG Member:					
23 Wood		Group B Section			
TAG Member:					
•					

	Section 2303—Minimum		Structural glued cross-				
51-50-2303	standards and quality.	2303.1.4	laminated timber				
<u>52 50 2505</u>	- community	2303.6	Nails and staples				
	Section 2304—General						
51-50-2304	construction requirements.	2304.1	Connectors and fasteners				
	·		Connection fire-resistance				
		2304.10.8	rating				
24 Glass and Glazing		Group B Section					
TAG Member:							
							This should be moved to WAC 51-
<u>51-50-2400</u>	Chapter 24—Glass and glazing.	2405.3	Screening				50-2405
	n Panel Products and Plaster	Group B Section		1	1		
TAG Member:							
			26 F	lastic			
TAG Member: Mark Sniffe	en						
							None
			27 Ele	ectrical			
TAG Member: Will Rodrig	uez						
	Section 2702—Emergency and					Agree with	
<u>51-50-2702</u>	standby power systems.	2702.1.5	Load duration	Same	Keep state amendment	recommendation	
			28 Mechan	ical Systems			
TAG Member: Andrew Kl	ein						
							None
			29 Plumbi	ng Systems			
TAG Member: Kim Barker							
					Incorporate 2021 model code		
					language with state		
					amendment to refer to "state		
					plumbing code" and delete		
	Chapter 29—Plumbing				references to codes not		Break up into WAC 51-50-2901
51-50-2900	systems.	2901.1	Scope	Same	adopted		and WAC 51-50-2902
		2901.2	Health codes	Same	Keep state amendment		
			Fixed guideway transit and				
		2901.3	passenger rail systems	Same	Keep state amendment		
		2902.1	Minimum number of fixtures	Same	Keep state amendment		

1	ı		1		
	Table 2902.1	MINIMUM NUMBER OF REQUIRED PLUMBING FIXTURES	Same	# State amendment includes references to R4, which is not adopted per WAC 51-50-0310. Consider omitting from the table. # The model code requirement for a kitchen sink in dwellings within the "other" column in the Table 2902.1. Recommend this requirement be incorporated in the Table instead of the current state amendment Section 2902.6, or at least a pointer be provided. # The model code requirement for drinking fountains is provided in a column in Table 2902.1. Recommend these requirements be incorporated in the Table instead of the current state amendment section 2902.5.X, or at least a pointer be provided.	
	2902.1.1.1	Private offices	Same	Keep state amendment	
	2902.1.1.2	Urinals in men's facilities	Same	Keep state amendment	
	2902.1.1.3	Urinals	Same	Keep state amendment	
	2902.1.4	Family or assisted-use toilet and bath fixtures	Same	Strike amendment. Model code addresses (and expands) the state language in Section 2902.1.2.	

		1			-
				Retain but modify state	
				amendment. The first three	
				exceptions in model code and	
				amendment are identical. The	
				model code does not include	
				the state exception #4. The	
				new model code exception #5	
				is like the state amendment	
				exception #5, so correlation of	
				language may be desired (state	
				uses "gender-neutral" and	
				model code uses "single-	
				user"). The model code added	
				a new Exception #6, that may	
				tie into the state amendment	
				#5 (language from model code	
				exception may be incorporated	
	2902.2	Separate facilities	Same	into the state amendment)	
		Family or assisted-use toilet		Strike amendment. Model	
		facilities serving as separate		code language includes all of	
	2902.2.1	facilities	Same	state amendment.	
	2502.2.1	raemaes	Sume	Retain aspects of state	
				amendment but consider	
				reviewing language of model	
				code Section 2902.1.2 for	
	2902.2.2	Gender-neutral facilities	Same	correlation or integration.	
		Table Head a radifices		The station of the station.	
				Retain state amendment for	
				Exception #3. Consider	
				reviewing state amendment	
				code language for body of	
				section. It seems very similar to	
				model code, but slightly	Note section numbers of model
		Employee and public toilet		different wording that does	code and state amendments
	2902.3	facilities	Same	not appear to affect the intent.	differs beginning here
	2902.3.1	Access	Same		

		1			
				Retain state amendment for	
				"or conveniently in a building	
				adjacent thereto on the same	
				property". However, the model	
				code adds two exceptions that	
				address our state exception,	
				and adds another one.	
				Recommend to modify the	
				amendment Exception	
		Location of toilet facilities in		language to reflect the model	Note Section 2902.3.3 in model
	2902.3.2		Come		
	2902.3.2	occupancies other than malls	Same	code language.	code
				Strike amendment. Model	
		Location of toilet facilities in		code include all of state	Note Section 2902.3.4 in model
	2902.3.3	malls	2902.3.4	amendment.	code
				Strike amendment. Model	
				code include all of state	Note Section 2902.3.5 in model
	2902.3.4	Pay facilities	2902.3.5	amendment.	code
				Chailes and an also and Adaptat	
				Strike amendment. Model	
				code include all of state	Note Section 2902.3.6 in model
	2902.3.5	Door locking	2902.3.6	amendment.	code
				Strike amendment. Model	
					Nata Castian 2002 2 2 in madel
				code include all of state	Note Section 2902.3.2 in model
	2902.3.6	Prohibited toilet room location	2902.3.7	amendment.	code
					Add model code language: "that
					designate the sex for separate
					facilities as required by Section
					2902.2" -Retain
					state language: "or indicate
					gender-neutral facilities." *Note,
					see also discussion in 2902.2
					regarding terms "single-user" v.
					"gender neutral".
					-Update code reference to
				Keep state amendment as	Section 1112.
	2902.4	Signage	Same	modified	

	I	1	I		
				Strike amendment. Model	-Retain state language: "or indicate gender-neutral facilities."
				code language appears to include all of state	*Note, see also discussion in 2902.2 regarding terms "single-
	2902.4.1	Directional signage	Same	amendment.	user" v. "gender neutral".
	2902.4.1	Directional signage	Same	amenument.	user v. gender neutrar .
	2000 5			Retain state amendment for "Drinking fountains shall be located on an accessible route. Drinking fountains shall not be	-Update code reference to
	2902.5	Drinking fountain location	Same	located in toilet rooms."	Section 1112.
	2902.5.1	Drinking fountain number	Same	Retain amendment, clarify correlation with model code Section 2902.6 Small Occupancies which reads "Drinking fountains shall not be required for an occupant load of 15 or fewer."	Note also, the model code includes this as a column in Table 2902.1. I would recommend this approach be mimicked, or at least a pointer from that table to this section.
		_		Retain amendment, model	
	2902.5.2	Multistory buildings	Same	code does not contain this section.	
				Retain amendment, model	
	2002 5 2	Developation times	C	code does not contain this	
	2902.5.3	Penal institutions	Same	section.	
	2902.5.4	Bottle filling stations	Same	Retain amendment, model code does not contain this section.	
				Retain amendment, model	
				code does not contain this	
	2902.5.4.1	Group E occupancies	Same	section.	
				Retain amendment, model code does not contain this	
	2902.5.4.2	Substitution	Same	section.	
	2002 5 4 2			Retain amendment, model code does not contain this	
	2902.5.4.3	Accessibility	Same	section.	

		I	1			<u> </u>	1
		2902.6	Dwelling units	2902.8	The model code includes this within the "other" column in the Table 2902.1. Recommend this requirement be incorporated there instead.		model code section 2902.6 is different, it refers to drinking fountain exception for small occupancies Model code added Section
		2902.7	Water	2902.9	Retain amendment, model code does not contain this section.		2902.7, so if state adopts that section, this will need to be renumbered
					See separate document	Accept recommendations	
	•		30 Elevators and	Conveying Sys	tems		
TAG Member: Andrew	Klein			, , ,			
<u>51-50-30050</u>	Section 3005—Machine rooms.	3005.2	Temperature control	3005.2	Keep state amendment		The title in 2021 IBC and 2018 WBC is "Venting;" title in WAC is "Temperature control"
<u>51-50-3006</u>	Section 3006—Elevators and conveying systems.	3006.3	Hoistway opening protection	3006.3	Keep state amendment	Accept recommendations	Amendment makes it clear that you need both.
			31 Special	Construction			
TAG Member: Sue Coff	fman						
51-50-3101	Section 3101—General.	3101.1	Scope	Same	Keep state amendment as modified to align with the new model code language.		Add add'l content from 2021
<u>51-50-3102</u>	Section 3102—Membrane structures.	3102.3	Type of construction	Same	Amendment no longer needed; model code addresses it		
		3102.6.1.1	Membrane	Same	Amendment no longer needed; model code addresses it		
<u>51-50-3103</u>	Temporary structures.	3103.1	General	Same	Keep state amendment but add add'l content from 2021		include Special event and umbrella structures
<u>51-50-3109</u>	Section 3109—Swimming pools, spas and other water recreation devices.	3109.1	General	Same	Keep state amendment		This Section incoproprates the International Swimming Pool and Spa Code
<u>51-50-3114</u>	Section 3114—Fixed guideway transit and passenger rail systems.	None		3115.1	Keep state amendment		This WAC section needs to be numbered
		3114.1	Means of egress	3115.2	Keep state amendment		Check where the section needs to be placed; new sections were added to the model code.

						Accept recommendations	Get L&I to coordinate on new 3115
		1	32 Encroachments Into	the Public Pig	ht Of Way	recommendations	3113
TAG Member: Sue Coffr	man		32 Liici Oaciiiileiits iiito	the Fublic Kig	iit-Oi-way		None
		•	33 Safeguards Di	uring Construc	tion		
TAG Member: Todd Bey	reuther						
51-50-3304	Section 3304—Site work	3304.2	Fire watch during construction	3314.1	Keep state amendment	Accept recommendations	
34 Reserved	1	1		1	1	T	1
			27.5 (
			35 Referen	ce Standards			
TAG Member: Mike Bar				I	1		T
<u>51-50-3500</u>	Chapter 35—Referenced standards.		Referenced standards	Same			
	ANSI-APA PRG 320		Standard for Performance Rated Cross laminated timber		Strike amendment, 2019 model code language is included		
			Fixed guideway transit and		Retain amendment, reference		•
	NFPA 130-17		passenger rail systems		2020 NFPA edition		
						Accept recommendations	
			Appendix A Empl	oyee Qualificat	tions		
							None
			Appendix B Bo	oard of Appeal	s		
							None
			Appendix C Group U	- Agriculture B	Buildings		
							None
			Appendix D	Fire Districts			-
TAG Member: Mark Sni	ffen		••				
51-50-4700	Appendix D—Fire districts.	D102.2.5	Structural fire rating	Same	Amendment no longer needed; model code addresses it.		
						Accept	
						recommendations	
		А	ppendix E Supplementary	Accessibility	Requirements		
TAG Member: Andrew I	Klein						None
Appendix F Rodentproof	fing	Group B Appendix					
Appendix G Flood-Resist	ant Construction	Group B Appendix					
Appendix H Signs		Group B Appendix					
Ĭ.							

		Group B	Group B					
Appendix I Patio Covers		Appendix	Appendix					
		Group B						
Appendix J Grading		Appendix	Appendix					
Appendix K Administrative Provisions								
TAG Member: Sue Coffman							None	
		Group B						
Appendix L Earthquake Rec	ording	Appendix	Appendix					
		Group B	Group B					
Appendix M Tsunami-Gene	rated D Flood Hazard	Appendix	Appendix					
Appendix N Relocatable Buildings								
TAG Member: Chris Seaman							None	